

Resistance Welding Electrodes

18-13




Fig. 18.2 - RWMA Standard Tapers

- The RWMA tapers cover a broader range than the Morse tapers (MT). These tapers are 0.600-in taper per foot and replace the Morse tapers which vary from 0.5986-in on the #1 MT to 0.6024-in on the #3 MT.
- The RWMA #4, #5 and #7 tapers are interchangeable with the MT #1, #2 and #3.